



Application No. 10/664,844
in reply to Notice of Missing Parts
dated January 22, 2004.

1/10




FIG. 1




FIG. 2




FIG. 3

TYPE IIA




FIG. 4A

TYPE IIIA




FIG. 4B

TYPE IVA




FIG. 5

TYPE VA




FIG. 6A

TYPE VI A




FIG. 6B




FIG. 7

TYPE IB




FIG. 8

TYPE IIB




FIG. 9A

TYPE IIIIB




FIG. 9B

10/10

TYPE IVB




FIG.10

TYPE VB




FIG.11A

TYPE VIB




FIG.11B